



Advancing
Battery Management

DSS-5000 HD PAC Release Notes

Software Update Revision B

Included in this update:

- Remove diode ripple test from RP129 app
- Add BMIS login and password
- Lowered the RPM rev range that is required during the system test
- Battery test code printing
- Fixed server contact nag screen
- Updated system test
- Modified verbiage for retest and inconclusive decision
- Fixed 'license file not valid' error after scanning invalid bar code
- Added Spanish and French manual translations
- Fixed various launcher crash bugs
- Other minor bug fixes